

AD-A087 588

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/6 13/13
NATIONAL DAM SAFETY PROGRAM. ROXBURY DAM (INVENTORY NUMBER 788)--ETC(U)
MAY 80 G KOCH


DACW51-79-C-0001

NL

UNCLASSIFIED

1 OF 2

AD
7087588



DELAWARE RIVER BASIN

ROXBURY DAM

DELAWARE COUNTY, NEW YORK

INVENTORY NO. N.Y. 788

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE
DISTRIBUTION STATEMENT
CONTRACT NO. DAAG01-80-2001

NEW YORK DISTRICT CORPS OF ENGINEERS

FEBRUARY, 1980

ORIGINAL CONTAINS COLOR PLATES; ALL DDC
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

80 8 4 264

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

REPORT DOCUMENTATION PAGE

READ INSTRUCTIONS
BEFORE COMPLETING FORM

1. REPORT NUMBER	2. GOVT ACCESSION NO. ADH087 588	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase 1 Inspection Report Roxbury Dam Delaware River Basin, Delaware County, NY Inventory No. NY 788		5. TYPE OF REPORT & PERIOD COVERED Phase 1 Inspection Report National Dam Safety Program
7. AUTHOR(s) George Koch, P.E.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental Conservation/ 50 Wolf Road Albany, NY 12233		8. CONTRACT OR GRANT NUMBER(s) DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Con- servation/ 50 Wolf Road Albany, New York 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (If different from Controlling Office) Department of the Army 26 Federal Plaza/ New York District, CofE New York, New York 10007		12. REPORT DATE 21 May 1980
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		

17. DISTRIBUTION STATEMENT (of the entire report, including abstract, if different from Report)

LEVEL

DTIC
ELECTRONIC
AUG 7 1980

18. SUPPLEMENTARY NOTES

ORIGINAL CONTAINS COLOR PLATES: ALL DDC
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

Dam Safety
National Dam Safety Program
Visual Inspection
Hydrology, Structural StabilityRoxbury Dam
Deleware County
Boxbury

20. ABSTRACT (Continue on reverse side if necessary and identify by block number)

This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization.

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which need to be evaluated and remedied.

DD FORM 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

ADA 087588

DDC FILE COPY

THIS DOCUMENT IS BEST QUALITY AVAILABLE
THE COPY FURNISHED TO YOU IS UNCLASSIFIED
SIGNIFICANT PORTIONS OF WHICH DO NOT
REPRODUCE

Using the Corps of Engineers' Screening Criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 36% of the Probable Maximum Flood (PMF) inflows. However, a flood wave analysis indicates that the water surface levels downstream of the dam would be approximately the same under a given storm regardless of whether or not the dam breaches. Since the spillway does not have sufficient capacity to pass the outflows from one half the PMF and breaching of the dam does not substantially increase the hazard to downstream residents from conditions which would occur just prior to dam breaching, the spillway is adjudged as inadequate.

The structural stability analysis performed for this dam indicates that for severe conditions (ice loading, water surface at top of dam) that the stability of the service spillway weir is questionable. Further investigation of the stability of this section is required.

There is a wet area at the toe in an oversteepened portion of the downstream slope. This wet area might be caused by leakage through the reservoir drain pipe, whose outlet is buried in the slope. Further investigation is required to determine the cause of this wet area and to design appropriate remedial treatment.

A number of other deficiencies were also noted on this structure. Among the repairs required brush and trees growing on the dam must be cut, the reservoir drain should be uncovered and made operable, deteriorated and cracked concrete on the service spillway should be repaired, and the wood framework across the entrance to the auxiliary spillway channel should be removed.

It is recommended that within 3 months of the date of the notification of the owner, additional investigations of the structural stability and of the wet area at the downstream toe should be commenced. Remedial actions deemed necessary based on the results of these investigations should be completed within 12 months of the notification. An emergency action plan for notification of downstream residents should be developed within 6 months. The other deficiencies noted above should be corrected within 12 months.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Approved	
WPI	
ME	
Chief of Engineers	
Washington, D.C.	

✓

A 23

11 21 May 80

10 George Koch

12 102

15 DACW51-79-C-0001

6

~~PHASE I INSPECTION REPORT~~
NATIONAL DAM SAFETY PROGRAM.
ROXBURY DAM (Inventory Number 788)
~~1425 Nov 44 788~~
DELAWARE RIVER BASIN
DELAWARE COUNTY, NEW YORK.
Phase I Inspection Report
TABLE OF CONTENTS

	<u>PAGE NO.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	4
2.1 GEOTECHNICAL DATA	4
2.2 DESIGN RECORDS	4
2.3 CONSTRUCTION RECORDS	4
2.4 OPERATION RECORD	4
2.5 EVALUATION OF DATA	4
3 VISUAL INSPECTION	5
3.1 FINDINGS	5
3.2 EVALUATION OF OBSERVATIONS	6
4 OPERATION AND MAINTENANCE PROCEDURES	7
4.1 PROCEDURE	7
4.2 MAINTENANCE OF DAM	7
4.3 WARNING SYSTEM IN EFFECT	7
4.4 EVALUATION	7

	<u>PAGE NO.</u>
5 HYDROLOGIC/HYDRAULIC	8
5.1 DRAINAGE AREA CHARACTERISTICS	8
5.2 ANALYSIS CRITERIA	8
5.3 SPILLWAY CAPACITY	8
5.4 RESERVOIR CAPACITY	8
5.5 FLOODS OF RECORD	8
5.6 OVERTOPPING POTENTIAL	9
5.7 EVALUATION	9
6 STRUCTURAL STABILITY	10
6.1 EVALUATION OF STRUCTURAL STABILITY	10
7 ASSESSMENT/RECOMMENDATIONS	11
7.1 ASSESSMENT	11
7.2 RECOMMENDED MEASURES	11

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. STABILITY COMPUTATIONS
- E. REFERENCES
- F. DRAWINGS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Roxbury Dam (I.D. No. NY 788)
State Located: New York
County: Delaware
Stream: Unnamed Tributary of Delaware River
Date of Inspection: November 1, 1979

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which need to be evaluated and remedied.

Using the Corps of Engineers' Screening Criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 36% of the Probable Maximum Flood (PMF) inflows. However, a flood wave analysis indicates that the water surface levels downstream of the dam would be approximately the same under a given storm regardless of whether or not the dam breaches. Since the spillway does not have sufficient capacity to pass the outflows from one half the PMF and breaching of the dam does not substantially increase the hazard to downstream residents from conditions which would occur just prior to dam breaching, the spillway is adjudged as inadequate.

The structural stability analysis performed for this dam indicates that for severe conditions (ice loading, water surface at top of dam) that the stability of the service spillway weir is questionable. Further investigation of the stability of this section is required.

There is a wet area at the toe in an oversteepened portion of the downstream slope. This wet area might be caused by leakage through the reservoir drain pipe, whose outlet is buried in the slope. Further investigation is required to determine the cause of this wet area and to design appropriate remedial treatment.

A number of other deficiencies were also noted on this structure. Among the repairs required brush and trees growing on the dam must be cut, the reservoir drain should be uncovered and made operable, deteriorated and cracked concrete on the service spillway should be repaired, and the wood framework across the entrance to the auxiliary spillway channel should be removed.



OVERVIEW
Roxbury Dam
I.D. No. HY 788

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
ROXBURY DAM
I.D. No. NY-788
#160D-646
DELAWARE RIVER BASIN
DELAWARE COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam

The Roxbury Dam (also known as Dales Lake Dam) is an earth dam with spillway channels on either end of the embankment.

The embankment is 36 feet high and 565 feet long. The crest is 12 feet wide. There is a cutoff wall under the embankment on the upstream end and there are concrete buttresses within the higher sections of the downstream portion of the embankment. The embankment slopes are 1 vertical on 2.5 horizontal on the upstream slope and 1 vertical on 1.5 horizontal on the downstream slope. The upstream slope is lined with rip-rap.

There are two spillway channels on this dam.. The channel on the eastern end of the dam is considered the service spillway. The upstream portion of this channel is a concrete structure which forms a 27.4 foot long rectangular weir. There is a 5 foot vertical drop beyond the crest of the weir. The remainder of the channel is masonry and laid-up stone. It extends to well beyond the toe of the dam where it joins the auxiliary spillway channel.

The channel at the western end of the embankment is considered to be the auxiliary spillway. The crest of this channel is 2.5 feet above the crest of the service spillway. This channel is 19 feet wide and consists of vertical laid-up stone walls and a masonry channel bottom.

There is a 12 inch diameter reservoir drain which passes through the embankment. Plans indicate that the pipe is about 150 feet long and is surrounded by at least 18 inches of concrete. The control valve for the pipe is located in a gate house which rises from the upstream toe of the embankment. The outlet to this pipe is apparently buried in the downstream slope.

b. Location

The Roxbury Dam is located in the Town of Roxbury off New York State Route 30. The lake is on a private road and is approximately one half mile northwest of the Village of Roxbury.

c. Size Classification

The dam is 36 feet high and has a maximum storage capacity of 101 acre-feet. Therefore, the dam is in the small size category as defined by the Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification

The dam is classified as "high" hazard due to the presence of a number of homes, businesses, and a school located in the village of Roxbury, downstream of the dam.

e. Ownership

The dam is owned by the Chemtex Corporation, 850 Third Avenue, New York, New York 10000. The caretaker of the property for Chemtex is George Boyle of Roxbury.

f. Purpose of Dam

The dam maintains the water level of Dales Lake, which is used for recreational purposes.

g. Design and Construction History

It could not be determined when this structure was originally constructed. The dam was reconstructed in 1912. At that time, a cutoff wall was constructed and additional fill was placed on top of the existing embankment. The auxiliary spillway was reconstructed and the reservoir drain was installed at this time. These modifications were designed by Prof. Charles H. Snow of New York University.

The dam was again reconstructed in 1976. At that time, both of the spillways were modified to increase the spillway capacity. These changes were designed by Richard P. Buck and Associates of Deposit, New York.

h. Normal Operating Procedures

Water flows over the ungated service spillway

1.3 PERTINENT DATA

a. Drainage Area (acres)	515
b. Elevation (USGS Datum)	
Top of Dam	1718.5
Auxiliary Spillway Crest (Western Channel)	1715.5
Service Spillway Crest (Eastern Channel)	1713.0
Invert of Reservoir Drain (estimated)	1692
c. Discharge at Dam (Water Surface @:)	cfs
Service Spillway (1718.5)	1096
Service Spillway (1715.5)	336
Auxiliary Spillway (1718.5)	267
Reservoir Drain - (1713.0)	28

<u>d. Reservoir-Surface Area</u>	(acres)
Top of Dam	7.8
Auxiliary Spillway Crest	7.0
Service Spillway Crest	5.8

<u>e. Storage Capacity</u>	(acre-feet)
Top of Dam	101.0
Auxiliary Spillway Crest	79.5
Service Spillway Crest	63.9

f. Dam
 Embankment Type - Earth, rock and miscellaneous rubble fill with a cutoff wall and concrete buttresses within the fill. Upstream slope lined with riprap and the downstream slope is grass covered.

Embankment Length (ft)	565
Slopes (V:H) Upstream	1 on 2.5
Downstream	1 on 1.5
Crest Width (ft)	12

g. Service Spillway
 Type: Concrete channel-rectangular weir. Five foot vertical drop beyond crest. Masonry and laid up stone channel beyond concrete section.
 Length: (Weir) 27.4 feet

h. Auxiliary Spillway
 Type: Masonry channel with vertical laid up stone sidewalls
 Bottom width (feet): 19

i. Reservoir Drain
 Type: 12 inch diameter pipe - 150 feet long. Pipe surrounded by 18 inches of concrete. Control valve in gate house which rises from upstream toe of embankment.

SECTION 2: ENGINEERING DATA

2.1 GEOTECHNICAL DATA

a. Geology

Roxbury Dam is located in the Catskill Mountain physiographic province of New York State. This province is a part of the Appalachian Plateau. The area is underlain by a great thickness of sedimentary rocks from the Devonian Era which lie almost horizontal. Glaciation and the action of streams have carved deep valleys in the flat lying rock. Summit elevations rise to between 3,000 and 4,000 feet. A review of the "Brittle Structures Map of the State of New York" indicated that there are no faults in the immediate vicinity of the dam. The surficial soils and features of the area are the result of glaciations during the Cenozoic Era, the last of which was the Wisconsin glaciation.

b. Subsurface Investigations

No records of any subsurface investigations performed for this structure were available. The only information which was available was taken from correspondence concerning the 1912 reconstruction of the dam and from a 1914 dam inspection report. These sources indicated that the soils in the vicinity of the dam were predominantly hardpan (glacial till).

2.2 DESIGN RECORDS

No records were available from the original design of the dam. There was some data available concerning the 1912 reconstruction. Prof. Charles H. Snow of New York University was the designer of these modifications which included the installation of the reservoir drain pipe and reconstruction of the auxiliary spillway channel. Plans and correspondence concerning the modifications were the only design records available for this reconstruction.

Information was also available concerning the 1976 reconstruction. Plans and a permit application prepared by Richard P. Buck and Associates were the primary sources of design data for this reconstruction.

2.3 CONSTRUCTION RECORDS

No information was available concerning the original construction of the dam. There were several photographs and some correspondence concerning the 1912 reconstruction. Plans from that reconstruction as well as the 1976 reconstruction have been included in Appendix F.

2.4 OPERATION RECORDS

There were no operation records available for this dam.

2.5 EVALUATION OF DATA

The data presented in this report was obtained from the Department of Environmental Conservation files. The information available appears to be reliable and adequate for Phase I inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of the Roxbury Dam was conducted on November 1, 1979. The weather was sunny and the temperature was in the fifties. The reservoir level at the time of the inspection was at the service spillway crest.

b. Embankment

Inspection of the embankment revealed several deficiencies. The most serious of these deficiencies was a wet area on the downstream slope. This wet area was located near the toe in a section where the slope was oversteepened. It appeared to be approximately in line with the reservoir drain pipe although the outlet to this pipe could not be located (it is probably buried). This wet area could therefore be caused by leakage from the pipe. Further investigation will be required to determine the exact cause of this wet area and whether the oversteepened slope in this area creates a stability problem.

There were other deficiencies noted on the embankment. Brush was growing on the upper portion of the upstream slope along the entire length of the dam. There was also brush and some trees growing on the lower part of the downstream slope. One large evergreen tree was growing at the eastern end of the service spillway. If this tree fell; it would block the spillway channel. In addition to the brush and trees, several animal burrow holes were noted on the downstream slope.

c. Service Spillway

Several deficiencies were observed on the service spillway. There was a horizontal crack which ran across the eastern abutment. A large vertical crack was also noted on the downstream face of the same abutment. Concrete had been placed on the surface of each abutment as part of the reconstruction in 1976. The surface of this new concrete was in good condition, but there was substantial honeycombing at the interface between the new and the old concrete. The concrete wall downstream of the west abutment was separated from the abutment by up to 1 1/2 inches at the top. The surface of the concrete on this wall as well as the surfaces on other sections which were not covered by new concrete in 1977 were deteriorated and spalling. The concrete which formed the spillway section itself appeared to be in satisfactory conditions. The remainder of the channel is rock lined, with some brush, grass and small trees growing in the lower portion of the channel.

d. Auxiliary Spillway

The auxiliary spillway also had several deficiencies. Among these is a wooden framework across the inlet to the spillway channel. This framework could trap debris and affect the capacity of the channel. The concrete abutments on either end of the channel were deteriorated. Beyond the crest, the channel was formed by vertical laid-up stone walls for the first 50 feet and was cut into existing ground below that point. The entire channel in this lower portion was filled with brush and small trees.

e. Reservoir Drain

The reservoir drain could not be observed. The gate house for the drain is located approximately 30 feet from the upstream slope. It was not possible to inspect the gate house during this inspection. No outlet of the reservoir drain could be located. As stated in paragraph 3.1b above, it was felt that the outlet to this pipe is buried and might be leaking, causing the wet area on the downstream slope.

3.2 EVALUATION OF OBSERVATIONS

Visual inspection revealed several deficiencies on this structure. The following items were noted:

1. A wet area near the toe of the downstream slope.
2. An oversteepened section of the downstream slope.
3. An inoperable buried outlet and possibly leaking of the reservoir drain.
4. Brush and trees growing on the embankment and in the spillway channels.
5. Animal burrow holes on the downstream slope.
6. Cracks and deterioration of the concrete on the service spillway channel.
7. A separation of the concrete wall from the west abutment of the service spillway.
8. A wood framework across the inlet to the auxiliary spillway channel.

SECTION 4: OPERATION and MAINTENANCE PROCEDURE

4.1 PROCEDURE

There are no established operating procedures for this structure.

4.2 MAINTENANCE OF DAM

The dam is maintained as required. The grass on the embankment is mowed regularly. During the inspection some of the brush in the service spillway channel was being cut. However, there is a need for increasing the maintenance efforts to correct many of the deficiencies outlined in section 3.2.

4.3 WARNING SYSTEM IN EFFECT

No apparent warning system is present.

4.4 EVALUATION

The operation procedures appear to be satisfactory. The maintenance procedures are deficient and increased maintenance efforts are required.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

Delineation of the watershed draining into the reservoir pool area was made using the USGS 7.5 minute quadrangle for Roxbury, New York. The drainage area is 515 acres and consists of open fields and wooded lands. Relief in the drainage area is moderate to steep with slopes of over 30 per cent in the northwestern portion of the drainage area.

5.2 ANALYSIS CRITERIA

The analysis of the floodwater retarding capability of this dam was performed using the Corps of Engineers HEC-1 computer program, Dam Safety version. This program develops an inflow hydrograph using the "Clark Unit Hydrograph" method and then uses the "Modified Puls" flood routing procedure. The spillway design flood selected was the Probable Maximum Flood (PMF) in accordance with the Recommended Guidelines of the U.S. Army Corps of Engineers.

5.3 SPILLWAY CAPACITY

The dam has a spillway channel at either end of the embankment. The spillway at the eastern end of the dam is considered to be the service spillway. The crest of this spillway channel is 2.5 feet below the crest of the auxiliary spillway channel. The service spillway was analyzed as a sharp-crested weir with a discharge coefficient (c) of 3.1. The auxiliary spillway channel was analyzed as a broad crested weir with a discharge coefficient (c) of 2.7.

The two spillway channels combined do not have sufficient capacity for discharging the peak outflow from either the PMF or one half the PMF. For the PMF, the peak inflow and the peak outflow are both approximately 4700 cfs. For one half the PMF, the peak inflow and the peak outflow are both about 2400 cfs. The computed spillway capacity for a water surface elevation at the top of the dam is 1362 cfs.

5.4 RESERVOIR CAPACITY

Storage capacity of the reservoir between the service spillway crest and the auxiliary spillway crest is 15.6 acre feet which is equivalent to a runoff depth of 0.36 inches over the drainage area. Additional surcharge storage capacity of 21.5 acre-feet is available between the auxiliary spillway crest and the top of the dam. This is equivalent to a runoff depth of 0.50 inches over the drainage area. The total storage capacity of the dam is 101 acre-feet.

5.5 FLOODS OF RECORD

There were no records available regarding the maximum known flood.

5.6 OVERTOPPING POTENTIAL

Analysis using the PMF and one half the PMF indicates that the dam does not have sufficient spillway capacity. For a PMF peak outflow of 4706 cfs, the dam would be overtopped to a computed depth of 1.33 feet. For the peak outflow from one half the PMF, the depth of overtopping would be 0.64 feet. The dam would be overtopped by all storms exceeding 36% of the PMF inflows.

5.7 EVALUATION

Using the Corps of Engineers screening criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 36% of the PMF inflows. However, a flood wave analysis indicates that under a given storm, downstream water surface elevations would be almost the same for a breach condition as they would be if the dam did not breach. The maximum difference in the water surface level between the breach and no breach condition would be less than 1 foot.

Since breaching of the dam does not substantially increase the hazard to downstream residents the spillway is adjudged to be inadequate, rather than a more severe assessment.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual observations of the structure revealed a number of deficiencies. A wet area near the toe of the downstream slope might be caused by leakage through the reservoir drain pipe, whose outlet is apparently buried in the slope. Among the other deficiencies noted were a section of the downstream slope which was steeper than adjacent sections, some deterioration of the concrete on the service spillway channel, and the gap between the downstream wall and the service spillway's concrete west abutment.

b. Data Review and Stability Evaluation

A stability analysis was performed for the service spillway weir. This weir is a concrete section which was modified during the reconstruction of 1976. Information used to perform the stability analysis was obtained from the 1976. The following conditions were analyzed;

- a. Normal conditions with the reservoir at spillway crest (elevation 1713)
- b. Reservoir level at spillway crest with an ice load of 5,000 lb/ft.
- c. Reservoir level at top of dam (elevation 1718.5)

The analyses performed (see Appendix D) indicate that the factors of safety against overturning and sliding are as follows:

<u>Case</u>	<u>Factors of Safety</u>	
	<u>Overturning</u>	<u>Sliding</u>
a. Reservoir at Service Spillway Crest	2.89	12.89
b. Same as (a) plus an ice load of 5,000 lb/ft.	1.00	0.68
c. Reservoir level at top of dam	1.9	1.12

The stability analyses indicate that the stability of the weir section is questionable. The safety factors fall to unacceptable levels when the section is subjected to extreme loading conditions (ice load, high reservoir level).

Further investigations and studies are required to better assess the stability of this section. Based on the results of these analyses, required modifications to the structure should be designed and implemented.

c. Seismic Stability

While there were no known faults in the vicinity of the dam, the history of this area indicates that its seismic probability is more than minor. Therefore, a seismic analysis was performed for the service spillway weir section assuming normal conditions and a seismic coefficient of 0.10. The safety factor against overturning with seismic considerations included was 2.06 and against sliding was 1.57.

Due to the lack of information concerning the embankment materials, no seismic analysis was performed for the embankment section.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase I inspection of the Roxbury Dam revealed that the spillway is inadequate and all storms which exceed 36 percent of the PMF inflow would overtop the dam. This overtopping could cause breaching of the dam; however, the resulting floodwave would not significantly increase the hazard to downstream residents from that which would exist just prior to breaching.

In addition to the inadequate spillway capacity, the structural stability analysis indicates that the stability of the service spillway weir is questionable when it is subjected to extreme loading conditions. Other deficiencies noted such as the wet area near the downstream slope and the oversteepened section of the downstream slope could present a hazard unless appropriate repairs are made. The fact that the reservoir drain is inoperable makes these deficiencies more critical.

b. Adequacy of Information

The information which was available for the preparation of this report was adequate.

c. Need for Additional Investigations

Additional investigation is required to find the cause of the wet area at the downstream toe of the embankment and to determine what remedial actions should be taken.

Further analysis of the structural stability of the service spillway weir is also needed. Based on the results of this analysis, required modifications to the structure should be designed and implemented.

d. Urgency

The investigations of the wet area and of the structural stability should be commenced within 3 months of the date of notification of the owner. Remedial actions deemed necessary based on the results of the investigations should be completed within 12 months of the notification. The other deficiencies noted below should also be corrected within 12 months.

7.2 RECOMMENDED MEASURES

- a. Upon completion of the investigation of the wet area near the toe of the slope appropriate remedial measures should be taken.
- b. Based on the results of the structural stability analysis, the service spillway weir should be modified as required.
- c. The oversteepened section of the downstream slope should be studied to determine if there is a stability problem.
- d. The reservoir drain should be made operable
- e. Brush and trees growing on the embankment and in the spillway channels should be cut and removed.

- f. Animal burrow holes on the downstream slope should be filled.
- g. The wood framework which is across the inlet to the auxiliary spillway channel should be removed.
- h. The deterioration of the concrete and separation of the concrete wall from the west abutment on the service spillway channel should be repaired.
- i. Develop an emergency action plan for notification of downstream residents and the proper authorities in the event of a dam failure.

APPENDIX A


PHOTOGRAPHS



Service Spillway Channel Looking Downstream - Note Large Tree on Left



Service Spillway Weir - Looking Upstream - Note Cracks on East Abutment



Service Spillway Weir - Note Honeycombed Concrete on Western Abutment



East Abutment on Service Spillway - Note Crack Running
Across Abutment



Crest of Auxiliary Spillway - Note Wood Framework Across Inlet



Auxiliary Spillway Channel - Note Brush and Birch Trees Growing in Channel



West Abutment of Service Spillway Weir - Note Separation Between Abutment and Wingwall



Exit Channel For Service Spillway - Note Grass and Brush in Channel



Crest of Auxiliary Spillway - Note Wood Framework Across Inlet



Auxiliary Spillway Channel - Note Brush and Birch Trees Growing in Channel



Downstream Slope - Note Trees Growing Near Downstream Toe



Wet Area and Oversteepened Section of Slope

1

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam ROXBURY DAM (DALES LAKE DAM)
Fed. I.D. # 788 DEC Dam No. 160D-646
River Basin DELAWARE
Location: Town ROXBURY County DELAWARE
Stream Name UNNAMED
Tributary of DELAWARE RIVER
Latitude (N) 42° 18.5' Longitude (W) 74° 34.2'
Type of Dam EARTH
Hazard Category C
Date(s) of Inspection 11/1/79
Weather Conditions 50° SUNNY
Reservoir Level at Time of Inspection AT SERVICE SPILLWAY CREST

b. Inspection Personnel R. WARRENDER W. LYNICK

c. Persons Contacted (Including Address & Phone No.) _____

d. History:

Date Constructed ? Date(s) Reconstructed 1912
1976
Designer C.H. SNOW / R.P. BUCK
Constructed By _____
Owner CHEMTEX CORP.

2) Embankment

a. Characteristics

- (1) Embankment Material EARTH
- (2) Cutoff Type PUDDLE WALL CUTOFF
- (3) Impervious Core NONE
- (4) Internal Drainage System NONE
- (5) Miscellaneous _____

b. Crest

- (1) Vertical Alignment SLIGHTLY UNEVEN - GENERAL SATISFACTORY
- (2) Horizontal Alignment CURVED
- (3) Surface Cracks NONE APPARENT
- (4) Miscellaneous _____

c. Upstream Slope

- (1) Slope (Estimate) (V:H) 1 ON 2 1/2
- (2) Undesirable Growth or Debris, Animal Burrows LIGHT BRUSH GROWING
ALONG ENTIRE SLOPE AT CREST ELEVATION - LARGE EVERGREEN
GROWING ON EAST ABUTMENT NEXT TO SPILLWAY
- (3) Sloughing, Subsidence or Depressions NONE

(4) Slope Protection LIGHT RIPRAP FROM CREST DOWN

(5) Surface Cracks or Movement at Toe NONE OBSERVED

d. Downstream Slope

(1) Slope (Estimate - V:H) 1 ON 1 1/2

(2) Undesirable Growth or Debris, Animal Burrows MOSTLY MOWED GRASS
SOME ANIMAL BURROWS & LIGHT BRUSH IN OVERSTEEPENED SECTION

(3) Sloughing, Subsidence or Depressions NONE

(4) Surface Cracks or Movement at Toe NONE

(5) Seepage WET AREA AT TOE - POSSIBLY DUE TO SEEPAGE
FROM BURIED RESERVOIR DRAIN OUTLET

(6) External Drainage System (Ditches, Trenches; Blanket) NONE

(7) Condition Around Outlet Structure POSSIBLE SEEPAGE
FROM RESERVOIR DRAIN

(8) Seepage Beyond Toe NONE

e. Abutments - Embankment Contact

(1) Erosion at Contact NONE

(2) Seepage Along Contact NONE

3) Drainage System

a. Description of System NONE

b. Condition of System

c. Discharge from Drainage System

4) Instrumentation (Momentum/Surveys, Observation Wells, Weirs, Piezometers, Etc.)

NONE

5) Reservoir

- a. Slopes SATISFACTORY
- b. Sedimentation NONE APPARENT
- c. Unusual Conditions Which Affect Dam WATER LEVEL ROSE & FELL ~~SEVERAL~~
ABOUT 1' SLIGHTLY EVERY FEW MINUTES - FAUCET EFFECT

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) STEEP HILL - PASSES
UNDER 2 SMALL ROADS & INTO ROXBURY
- b. Seepage, Unusual Growth NONE
- c. Evidence of Movement Beyond Toe of Dam NONE
- d. Condition of Downstream Channel ROCK LINED (OUTCROP) CHANNEL
DOWN OFF THE HILL - ONE WATERFALL IN CHANNEL

7) Spillway(s) (Including Discharge Conveyance Channel)

- a. General ONE SPILLWAY CHANNEL AT EITHER END OF STRUCTURE
SERVICE AT EASTERN END AUXILIARY ON WESTERN.
- b. Condition of Service Spillway MEASURED DIMENSIONS 27.4' ACROSS 5'10" HIGH
NEW CONCRETE OVER OLD INTERFACE IS HONEY COMBED
CHANNEL IS ROCK LINED WITH LIGHT BRUSH AND TREES
GROWING UP THROUGH INVERT FOR ENTIRE CHANNEL

c. Condition of Auxiliary Spillway IRREGULAR PLACED STONE - INVERT
UPSTREAM OF WEIR SATISFACTORY - DOWNSTREAM OF WEIR
CHANNEL IS FULL OF BRUSH & TREES. STONE WALLS FOR
FIRST 50' THEN CUT IN EARTH FOR THE REMAINDER

d. Condition of Discharge Conveyance Channel _____

8) Reservoir Drain/Outlet

Type: Pipe ☒ Conduit _____ Other _____

Material: Concrete _____ Metal _____ Other _____

Size: 12" Length 150'

Invert Elevations: Entrance _____ Exit _____

Physical Condition (Describe): _____ Unobservable ☒

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: _____

Means of Control: Gate ☒ Valve _____ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other ?

Present Condition (Describe): COULD NOT BE OBSERVED

OUTLET COULD NOT BE LOCATED.

9) Structural

- a. Concrete Surfaces NEW SURFACES WERE SATISFACTORY- THE OLD ONES WERE DETERIORATED
- b. Structural Cracking LARGE HORIZONTAL CRACK RUNNING ALONG EAST ABUT. WALL ON SERVICE SPILLWAY ALSO HAS A LARGE CRACK EXTENDING FROM TOP OF ABUTMENT TO THE BOTTOM
- c. Movement - Horizontal & Vertical Alignment (Settlement) NONE APPARENT
- d. Junctions with Abutments or Embankments AUX. SPILLWAY - CONCRETE ABUTMENTS DETERIORATED ON SURFACE
SERVICE SPILLWAY - RIGHT DOWNSTREAM WALL ENTIRELY SEPARATED BY UP TO 1 1/2" FROM ^{WEST} SPILLWAY ABUTMENT - ALSO HAS A VOID ON EMBANKMENT SIDE WHICH RUNS THE LENGTH OF THE WALL.
- e. Drains - Foundation, Joint, Face NONE
- f. Water Passages, Conduits, Sluices DRAIN WAS UNOBSERVABLE
- g. Seepage or Leakage DRAIN SEEMED TO BE LEAKING

- h. Joints - Construction, etc. HONEY COMBING WHERE NEW
CONCRETE WAS PLACED OVER OLD CONCRETE
- i. Foundation _____
- j. Abutments _____
- k. Control Gates _____
- l. Approach & Outlet Channels SERVICE SPILLWAY - BATTERED CONCRETE
WALL & THEN FIELDSTONE WALL - ADEQUATELY BATERED
AUX. SPILLWAY - FIELDSTONE SOMEWHAT MOVEABLE BUT BATTERED
DOWNSTREAM END OF CHANNEL IS CRUMBLING
- m. Energy Dissipators (Plunge Pool, etc.) SERVICE SPILLWAY - NATURAL
DROP ONTO CONCRETE APRON AT 4 OLD PIERS
- n. Intake Structures _____
- o. Stability _____
- p. Miscellaneous _____

APPENDIX C

HYDROLOGIC/HYDRAULIC
ENGINEERING DATA AND COMPUTATIONS

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>1718.5</u>	<u>7.80</u>	<u>101</u>
2) Design High Water (Max. Design Pool)	<u> </u>	<u> </u>	<u> </u>
3) Auxiliary Spillway Crest	<u>1715.5</u>	<u>7.00</u>	<u>79.5</u>
4) Pool Level with Flashboards	<u> </u>	<u> </u>	<u> </u>
5) Service Spillway Crest	<u>1713</u>	<u>5.80</u>	<u>64</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u> </u>
2) Service Spillway @ Maximum High Water	<u>1095.6</u>
3) Auxiliary Spillway @ Maximum High Water	<u>266.6</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>335.7</u>
5) Low Level Outlet At Maximum High Water	<u>31.9</u>
6) Total (of all facilities) @ Maximum High Water	<u>1362.2</u>
7) Maximum Known Flood	<u> </u>

CREST:

ELEVATION: 1718.5Type: EARTHWidth: 12Length: 565Spillover SERVICE - CONCRETE WEIR AUXILIARY - EARTH BROAD CREST WEIRLocation EAST ENDWEST END

SPILLWAY:

PRINCIPAL

EMERGENCY

1713Elevation 1715.5SHARP CRESTED 1' WIDEType BROAD CRESTED27.4'Width 19'

Type of Control

✓

Uncontrolled

✓

Controlled:

Type
(Flashboards; gate)

Number

Size/Length

Invert Material

Anticipated Length
of operating service

Chute Length

73'Height Between Spillway Crest
& Approach Channel Invert
(Weir Flow)< 1'

OUTLET STRUCTURES/EMERGENCY DRAWDOWN FACILITIES:

Type: Gate ☒ Sluice _____ Conduit _____ Penstock _____Shape : ROUNDSize: 12 INCHElevations: Entrance Invert 1690±Exit Invert ?

Tailrace Channel: Elevation _____

HYDROMETEROLOGICAL GAGES:

Type : NONE

Location: _____

Records:

Date - _____

Max. Reading - _____

FLOOD WATER CONTROL SYSTEM:

Warning System: NONE

Method of Controlled Releases (mechanisms):

POSSIBLY RESERVOIR DRAIN BUT IT APPEARS
TO BE IN OPERABLE

DRAINAGE AREA: 555 ACRES

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: FOREST & GOLF COURSE

Terrain - Relief: STEEP, FORESTED

Surface - Soil: _____

Runoff Potential (existing or planned extensive alterations to existing
(surface or subsurface conditions)

NONE

Potential Sedimentation problem areas (natural or man-made; present or future)

NONE

Potential Backwater problem areas for levels at maximum storage capacity
including surcharge storage:

NONE

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the
Reservoir perimeter:

Location: NONE

Elevation: _____

Reservoir:

Length @ Maximum Pool _____ (Miles)

Length of Shoreline (@ Spillway Crest) _____ (Miles)

PROJECT GRID

JOB	ROXBURY DAM	SHEET NO.	1	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC / HYDRAULIC DAM			COMPUTED BY	RLW	DATE	2/13/80
DRAINAGE AREA = 515 ACRES = .80 SQ. MI							
ROXBURY QUADRANGLE 5.61 IN ² → 515 ACRES							
CLARK HYDROGRAPH COEFFICIENTS							
L = 900 FT + 1000 FT = 8100 FT → 1.53 MI.							
S ₊ = .5%							
S _{0.5} = $\frac{2500 - 1713}{1.29} = 610 \text{ FT/MI.}$							
$TC = \frac{(5.33)(L^{.602})(S_+^{.231})}{S_{0.5}^{.148}} = \frac{(5.33)(1.53^{.602})(.5^{.231})}{610^{.148}} = .33 \quad \text{ROUND TO } TC = .5$							
$R = \frac{(7.0)(L^{.339})(S_+^{.258})}{S_{0.5}^{.185}} = \frac{17.6(1.53^{.339})(.5^{.258})}{610^{.185}} = .068 \quad \text{ROUND TO } R = .1$							
TP-40 PMP RAINFALL							
PMP RAINFALL (6 HOUR - 10 SQ MI) = 23 IN							
6 HR = 100%							
24 HR = 119%							
12 HR = 111%							
48 HR = 128%							
TRSPC = $1 - \frac{.3008}{1.89 - .19718} = .686$							
LOSS DATA: 1.0" CONTINUOUS = .1"							
BASE FLOW = 2 CFS							

PROJECT GRID

JOB	ROXBURY DAM	SHEET NO.	2	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC / HYDRAULIC COMPUTATIONS			COMPUTED BY	RLW	DATE	2/13/80
<u>ELEVATIONS</u>							
TOP OF DAM		1718.5					
AUX. SPILLWAY CREST		1715.5					
SERVICE SPILLWAY CREST		1713.0					
<u>SURFACE AREAS AT VARIOUS ELEVATIONS</u>							
<u>ELEVATION</u>		<u>SURFACE AREA (ACRES)</u>					
1720.5		8.19*					
1718.5		7.80					
1717.5		7.50					
1715.5		7.00					
1713.0		5.80					
<p>* THIS SURFACE AREA WAS PLANIMETERED FROM RICHARD BUCK PLANS DATED 6/16/76. OTHER ELEVATIONS AND SURFACE AREAS WERE TAKEN FROM THE 1976 APPLICATION FOR PERMIT.</p>							

PROJECT GRID

JOB	ROXBURY DAM	SHEET NO.	3	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC / HYDRAULIC COMPUTATIONS			COMPUTED BY	RLW	DATE	2/13/80
<u>DISCHARGE CAPACITY</u>							
<u>SERVICE SPILLWAY CHANNEL</u>							
USE $C=3.1$ $L=27.4'$							
WATER SURFACE AT AUXILIARY SPILLWAY CREST							
$Q = (3.1)(27.4)(2.5)^{3/2} = 335.7 \text{ cfs}$							
WATER SURFACE AT TOP OF DAM							
$Q = (3.1)(27.4)(5.5)^{3/2} = 1095.6 \text{ cfs}$							
<u>AUXILIARY SPILLWAY CHANNEL</u>							
WATER SURFACE AT TOP OF DAM							
USE $C=2.7$ $L=19$							
$Q = (2.7)(19)(3)^{3/2} = 266.6 \text{ cfs}$							
<u>RESERVOIR DRAIN CAPACITY</u>							
WATER SURFACE AT SERVICE SPILLWAY CREST							
$Q = .78 \sqrt{2(32.2)(30.5)} = 28.3 \text{ cfs}$							

 NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTION BUREAU

 FLOOD ANALYSIS FACTS (C-10)
 D-3 SAFETY VERIFICATION JUL 7 1973
 LAST MODIFICATION 2 FEB 70
 MODIFIED FOR RIVER 4 (A-7)

 1. ANALYSIS
 2. A. IF VIF RATES - ANALYSIS
 3. A. DATE
 4. H. 200
 5. H. 5
 6. J. 1 3 1
 7. J. 1.5 1.5
 8. K. 0 1
 9. K. 1
 10. K. 1 0 .8
 11. P. 0 20 100 110 119 128
 12. T. 1 .06
 13. V. .2 .1
 14. X. 2 1 3.5
 15. K. 1 1
 16. K. ROUTED HYDROGRAPH AT DAM NO BREACH
 17. Y. 1 1 1
 18. Y. 1
 19. Y. 1715 1715.5 1717 1718.5
 20. Y. 0 336 774 1362
 21. S. 0 63.2 72.5 93.4 101
 22. S. 1.3 1713 1715.5 1717.5 1718.5
 23. S. 1713
 24. S. 1713.5 3.0 1.5 615
 25. K. 1 50
 26. A. LOCATION, TIME OF DAY
 27. Y. 1 1 1
 28. Y. 1
 29. Y. .02 .25 .35 1682 1720 50 .73
 30. Y. .02 .25 .35 1682 1720 50 .73
 31. Y. .02 .25 .35 1682 1720 50 .73
 32. Y. .02 .25 .35 1682 1720 50 .73
 33. Y. .02 .25 .35 1682 1720 50 .73
 34. Y. .02 .25 .35 1682 1720 50 .73
 35. Y. .02 .25 .35 1682 1720 50 .73
 36. Y. .02 .25 .35 1682 1720 50 .73
 37. Y. .02 .25 .35 1682 1720 50 .73
 38. Y. .02 .25 .35 1682 1720 50 .73
 39. Y. .02 .25 .35 1682 1720 50 .73
 40. Y. .02 .25 .35 1682 1720 50 .73
 41. Y. .02 .25 .35 1682 1720 50 .73
 42. Y. .02 .25 .35 1682 1720 50 .73
 43. Y. .02 .25 .35 1682 1720 50 .73
 44. Y. .02 .25 .35 1682 1720 50 .73
 45. Y. .02 .25 .35 1682 1720 50 .73
 46. Y. .02 .25 .35 1682 1720 50 .73
 47. Y. .02 .25 .35 1682 1720 50 .73
 48. Y. .02 .25 .35 1682 1720 50 .73
 49. Y. .02 .25 .35 1682 1720 50 .73
 50. Y. .02 .25 .35 1682 1720 50 .73
 51. Y. .02 .25 .35 1682 1720 50 .73
 52. Y. .02 .25 .35 1682 1720 50 .73
 53. Y. .02 .25 .35 1682 1720 50 .73
 54. Y. .02 .25 .35 1682 1720 50 .73
 55. Y. .02 .25 .35 1682 1720 50 .73
 56. Y. .02 .25 .35 1682 1720 50 .73
 57. Y. .02 .25 .35 1682 1720 50 .73
 58. Y. .02 .25 .35 1682 1720 50 .73
 59. Y. .02 .25 .35 1682 1720 50 .73
 60. Y. .02 .25 .35 1682 1720 50 .73
 61. Y. .02 .25 .35 1682 1720 50 .73
 62. Y. .02 .25 .35 1682 1720 50 .73
 63. Y. .02 .25 .35 1682 1720 50 .73
 64. Y. .02 .25 .35 1682 1720 50 .73
 65. Y. .02 .25 .35 1682 1720 50 .73
 66. Y. .02 .25 .35 1682 1720 50 .73
 67. Y. .02 .25 .35 1682 1720 50 .73
 68. Y. .02 .25 .35 1682 1720 50 .73
 69. Y. .02 .25 .35 1682 1720 50 .73
 70. Y. .02 .25 .35 1682 1720 50 .73
 71. Y. .02 .25 .35 1682 1720 50 .73
 72. Y. .02 .25 .35 1682 1720 50 .73
 73. Y. .02 .25 .35 1682 1720 50 .73
 74. Y. .02 .25 .35 1682 1720 50 .73
 75. Y. .02 .25 .35 1682 1720 50 .73
 76. Y. .02 .25 .35 1682 1720 50 .73
 77. Y. .02 .25 .35 1682 1720 50 .73
 78. Y. .02 .25 .35 1682 1720 50 .73
 79. Y. .02 .25 .35 1682 1720 50 .73
 80. Y. .02 .25 .35 1682 1720 50 .73
 81. Y. .02 .25 .35 1682 1720 50 .73
 82. Y. .02 .25 .35 1682 1720 50 .73
 83. Y. .02 .25 .35 1682 1720 50 .73
 84. Y. .02 .25 .35 1682 1720 50 .73
 85. Y. .02 .25 .35 1682 1720 50 .73
 86. Y. .02 .25 .35 1682 1720 50 .73
 87. Y. .02 .25 .35 1682 1720 50 .73
 88. Y. .02 .25 .35 1682 1720 50 .73
 89. Y. .02 .25 .35 1682 1720 50 .73
 90. Y. .02 .25 .35 1682 1720 50 .73
 91. Y. .02 .25 .35 1682 1720 50 .73
 92. Y. .02 .25 .35 1682 1720 50 .73
 93. Y. .02 .25 .35 1682 1720 50 .73
 94. Y. .02 .25 .35 1682 1720 50 .73
 95. Y. .02 .25 .35 1682 1720 50 .73
 96. Y. .02 .25 .35 1682 1720 50 .73
 97. Y. .02 .25 .35 1682 1720 50 .73
 98. Y. .02 .25 .35 1682 1720 50 .73
 99. Y. .02 .25 .35 1682 1720 50 .73
 100. Y. .02 .25 .35 1682 1720 50 .73

INFLUX HYDROGRAPH

1682 285 1682

31	1625	1635	630	1720
32	1	1000		
33	K1 LOSTFIELD HILLSIDE			
34			1	
35				
36	.05	.05	1617	1000
37	1600	110	1620	115
38	1620	220	1660	1617
39	1	2000		125
40	L1 LUGGERS ROAD CROSSING			
41		1	1	
42	1			
43	.05	1515	1600	1000
44	1600	1560	780	1520
45	1520	1540	1200	1600
46	1	3000		
47	L1 LUGGERS JUNCTION WITH EAST BRANCH OF DELAWARE			
48		1	1	
49				
50	.05	1470	1520	1000
51	1520	1500	1050	1475
52	1475	1500	2150	1520
53				
54				
55				
56				
57				
58				

 NEW YORK STATE
 DEPT OF ENVIRONMENTAL CONSERVATION
 FLOOD PROTECTION BUREAU

RUN DATE 02/25/80

WTA 1 1 1 1 1
 INFORMATION - ANALYSIS
 DATE 2/26/80

JOB SPECIFICATION
 IPR IMIN METRC IPLT IPKT NSTAIR
 0.00 0 0 0 0 0
 MKT LKOPT TRACE
 5 0 0 0

 11-PLAN ANALYSES TO BE PERFORMED
 PLAN=1 PORTID=3 LATID=1
 RT= 0.35 0.35 1.00

3IN-AREA KINIFF COMPUTATION

INFLOW HYDROGRAPH
 ISTAG IPRP IECUP ITAPE JPLT JPRT INAME ISTAGE IAUTO
 1 0 0 0 0 0 1 0 0

HYDROGRAPH DATA
 IPRD IPRG IAREA SHAP TRFSDA TRSFC RATIO ISHOW ISAVE LOCAL
 1 0 0 0.50 3. 0.89 0.69 0. 0 1 0

PRECIP DATA
 DATE PMS P6 M12 R24 R48 R72 R96
 23.00 100.00 111.00 119.00 128.00 0. 0.

LOSS DATA
 LEGD STAGE DLYR RTVAL ERRAIN STRKS RTINK STRIL CNSTL ALSMX RTIMP
 0 0. 0. 1.00 0. 0. 0. 1.00 0.06 0. 0.

UNIT HYDROGRAPH DATA
 PR= 0.50 1= 0.10 IITA= 0

RECESSION DATA
 STAGE= 2.00 UNCH= 1.00 RTIRR= 3.50

UNIT HYDROGRAPH 5 END=0.00 PERIOD ORDTATES, LAG= 0.31 HOURS, CP= 0.74 VOL= 1.00
 23. 10. 1121. 45.

END-OF-PERIOD FLOW
 CURD 1
 CURD 2
 CURD 3
 CURD 4
 CURD 5
 CURD 6
 CURD 7
 CURD 8
 CURD 9
 CURD 10
 CURD 11
 CURD 12
 CURD 13
 CURD 14
 CURD 15
 CURD 16
 CURD 17
 CURD 18
 CURD 19
 CURD 20
 CURD 21
 CURD 22
 CURD 23
 CURD 24
 CURD 25
 CURD 26
 CURD 27
 CURD 28
 CURD 29
 CURD 30
 CURD 31
 CURD 32
 CURD 33
 CURD 34
 CURD 35
 CURD 36
 CURD 37
 CURD 38
 CURD 39
 CURD 40
 CURD 41
 CURD 42
 CURD 43
 CURD 44
 CURD 45
 CURD 46
 CURD 47
 CURD 48
 CURD 49
 CURD 50
 CURD 51
 CURD 52
 CURD 53
 CURD 54
 CURD 55
 CURD 56
 CURD 57
 CURD 58
 CURD 59
 CURD 60
 CURD 61
 CURD 62
 CURD 63
 CURD 64
 CURD 65
 CURD 66
 CURD 67
 CURD 68
 CURD 69
 CURD 70
 CURD 71
 CURD 72
 CURD 73
 CURD 74
 CURD 75
 CURD 76
 CURD 77
 CURD 78
 CURD 79
 CURD 80
 CURD 81
 CURD 82
 CURD 83
 CURD 84
 CURD 85
 CURD 86
 CURD 87
 CURD 88
 CURD 89
 CURD 90
 CURD 91
 CURD 92
 CURD 93
 CURD 94
 CURD 95
 CURD 96
 CURD 97
 CURD 98
 CURD 99
 CURD 100
 CURD 101
 CURD 102
 CURD 103
 CURD 104
 CURD 105
 CURD 106
 CURD 107
 CURD 108
 CURD 109
 CURD 110
 CURD 111
 CURD 112
 CURD 113
 CURD 114
 CURD 115
 CURD 116
 CURD 117
 CURD 118
 CURD 119
 CURD 120
 CURD 121
 CURD 122
 CURD 123
 CURD 124
 CURD 125
 CURD 126
 CURD 127
 CURD 128
 CURD 129
 CURD 130
 CURD 131
 CURD 132
 CURD 133
 CURD 134
 CURD 135
 CURD 136
 CURD 137
 CURD 138
 CURD 139
 CURD 140
 CURD 141
 CURD 142
 CURD 143
 CURD 144
 CURD 145
 CURD 146
 CURD 147
 CURD 148
 CURD 149
 CURD 150
 CURD 151
 CURD 152
 CURD 153
 CURD 154
 CURD 155
 CURD 156
 CURD 157
 CURD 158
 CURD 159
 CURD 160
 CURD 161
 CURD 162
 CURD 163
 CURD 164
 CURD 165
 CURD 166
 CURD 167
 CURD 168
 CURD 169
 CURD 170
 CURD 171
 CURD 172
 CURD 173
 CURD 174
 CURD 175
 CURD 176
 CURD 177
 CURD 178
 CURD 179
 CURD 180
 CURD 181
 CURD 182
 CURD 183
 CURD 184
 CURD 185
 CURD 186
 CURD 187
 CURD 188
 CURD 189
 CURD 190
 CURD 191
 CURD 192
 CURD 193
 CURD 194
 CURD 195
 CURD 196
 CURD 197
 CURD 198
 CURD 199
 CURD 200
 CURD 201
 CURD 202
 CURD 203
 CURD 204
 CURD 205
 CURD 206
 CURD 207
 CURD 208
 CURD 209
 CURD 210
 CURD 211
 CURD 212
 CURD 213
 CURD 214
 CURD 215
 CURD 216
 CURD 217
 CURD 218
 CURD 219
 CURD 220
 CURD 221
 CURD 222
 CURD 223
 CURD 224
 CURD 225
 CURD 226
 CURD 227
 CURD 228
 CURD 229
 CURD 230
 CURD 231
 CURD 232
 CURD 233
 CURD 234
 CURD 235
 CURD 236
 CURD 237
 CURD 238
 CURD 239
 CURD 240
 CURD 241
 CURD 242
 CURD 243
 CURD 244
 CURD 245
 CURD 246
 CURD 247
 CURD 248
 CURD 249
 CURD 250
 CURD 251
 CURD 252
 CURD 253
 CURD 254
 CURD 255
 CURD 256
 CURD 257
 CURD 258
 CURD 259
 CURD 260
 CURD 261
 CURD 262
 CURD 263
 CURD 264
 CURD 265
 CURD 266
 CURD 267
 CURD 268
 CURD 269
 CURD 270
 CURD 271
 CURD 272
 CURD 273
 CURD 274
 CURD 275
 CURD 276
 CURD 277
 CURD 278
 CURD 279
 CURD 280
 CURD 281
 CURD 282
 CURD 283
 CURD 284
 CURD 285
 CURD 286
 CURD 287
 CURD 288
 CURD 289
 CURD 290
 CURD 291
 CURD 292
 CURD 293
 CURD 294
 CURD 295
 CURD 296
 CURD 297
 CURD 298
 CURD 299
 CURD 300
 CURD 301
 CURD 302
 CURD 303
 CURD 304
 CURD 305
 CURD 306
 CURD 307
 CURD 308
 CURD 309
 CURD 310
 CURD 311
 CURD 312
 CURD 313
 CURD 314
 CURD 315
 CURD 316
 CURD 317
 CURD 318
 CURD 319
 CURD 320
 CURD 321
 CURD 322
 CURD 323
 CURD 324
 CURD 325
 CURD 326
 CURD 327
 CURD 328
 CURD 329
 CURD 330
 CURD 331
 CURD 332
 CURD 333
 CURD 334
 CURD 335
 CURD 336
 CURD 337
 CURD 338
 CURD 339
 CURD 340
 CURD 341
 CURD 342
 CURD 343
 CURD 344
 CURD 345
 CURD 346
 CURD 347
 CURD 348
 CURD 349
 CURD 350
 CURD 351
 CURD 352
 CURD 353
 CURD 354
 CURD 355
 CURD 356
 CURD 357
 CURD 358
 CURD 359
 CURD 360
 CURD 361
 CURD 362
 CURD 363
 CURD 364
 CURD 365
 CURD 366
 CURD 367
 CURD 368
 CURD 369
 CURD 370
 CURD 371
 CURD 372
 CURD 373
 CURD 374
 CURD 375
 CURD 376
 CURD 377
 CURD 378
 CURD 379
 CURD 380
 CURD 381
 CURD 382
 CURD 383
 CURD 384
 CURD 385
 CURD 386
 CURD 387
 CURD 388
 CURD 389
 CURD 390
 CURD 391
 CURD 392
 CURD 393
 CURD 394
 CURD 395
 CURD 396
 CURD 397
 CURD 398
 CURD 399
 CURD 400
 CURD 401
 CURD 402
 CURD 403
 CURD 404
 CURD 405
 CURD 406
 CURD 407
 CURD 408
 CURD 409
 CURD 410
 CURD 411
 CURD 412
 CURD 413
 CURD 414
 CURD 415
 CURD 416
 CURD 417
 CURD 418
 CURD 419
 CURD 420
 CURD 421
 CURD 422
 CURD 423
 CURD 424
 CURD 425
 CURD 426
 CURD 427
 CURD 428
 CURD 429
 CURD 430
 CURD 431
 CURD 432
 CURD 433
 CURD 434
 CURD 435
 CURD 436
 CURD 437
 CURD 438
 CURD 439
 CURD 440
 CURD 441
 CURD 442
 CURD 443
 CURD 444
 CURD 445
 CURD 446
 CURD 447
 CURD 448
 CURD 449
 CURD 450
 CURD 451
 CURD 452
 CURD 453
 CURD 454
 CURD 455
 CURD 456
 CURD 457
 CURD 458
 CURD 459
 CURD 460
 CURD 461
 CURD 462
 CURD 463
 CURD 464
 CURD 465
 CURD 466
 CURD 467
 CURD 468
 CURD 469
 CURD 470
 CURD 471
 CURD 472
 CURD 473
 CURD 474
 CURD 475
 CURD 476
 CURD 477
 CURD 478
 CURD 479
 CURD 480
 CURD 481
 CURD 482
 CURD 483
 CURD 484
 CURD 485
 CURD 486
 CURD 487
 CURD 488
 CURD 489
 CURD 490
 CURD 491
 CURD 492
 CURD 493
 CURD 494
 CURD 495
 CURD 496
 CURD 497
 CURD 498
 CURD 499
 CURD 500
 CURD 501
 CURD 502
 CURD 503
 CURD 504
 CURD 505
 CURD 506
 CURD 507
 CURD 508
 CURD 509
 CURD 510
 CURD 511
 CURD 512
 CURD 513
 CURD 514
 CURD 515
 CURD 516
 CURD 517
 CURD 518
 CURD 519
 CURD 520
 CURD 521
 CURD 522
 CURD 523
 CURD 524
 CURD 525
 CURD 526
 CURD 527
 CURD 528
 CURD 529
 CURD 530
 CURD 531
 CURD 532
 CURD 533
 CURD 534
 CURD 535
 CURD 536
 CURD 537
 CURD 538
 CURD 539
 CURD 540
 CURD 541
 CURD 542
 CURD 543
 CURD 544
 CURD 545
 CURD 546
 CURD 547
 CURD 548
 CURD 549
 CURD 550
 CURD 551
 CURD 552
 CURD 553
 CURD 554
 CURD 555
 CURD 556
 CURD 557
 CURD 558
 CURD 559
 CURD 560
 CURD 561
 CURD 562
 CURD 563
 CURD 564
 CURD 565
 CURD 566
 CURD 567
 CURD 568
 CURD 569
 CURD 570
 CURD 571
 CURD 572
 CURD 573
 CURD 574
 CURD 575
 CURD 576
 CURD 577
 CURD 578
 CURD 579
 CURD 580
 CURD 581
 CURD 582
 CURD 583
 CURD 584
 CURD 585
 CURD 586
 CURD 587
 CURD 588
 CURD 589
 CURD 590
 CURD 591
 CURD 592
 CURD 593
 CURD 594
 CURD 595
 CURD 596
 CURD 597
 CURD 598
 CURD 599
 CURD 600
 CURD 601
 CURD 602
 CURD 603
 CURD 604
 CURD 605
 CURD 606
 CURD 607
 CURD 608
 CURD 609
 CURD 610
 CURD 611
 CURD 612
 CURD 613
 CURD 614
 CURD 615
 CURD 616
 CURD 617
 CURD 618
 CURD 619
 CURD 620
 CURD 621
 CURD 622
 CURD 623
 CURD 624
 CURD 625
 CURD 626
 CURD 627
 CURD 628
 CURD 629
 CURD 630
 CURD 631
 CURD 632
 CURD 633
 CURD 634
 CURD 635
 CURD 636
 CURD 637
 CURD 638
 CURD 639
 CURD 640
 CURD 641
 CURD 642
 CURD 643
 CURD 644
 CURD 645
 CURD 646
 CURD 647
 CURD 648
 CURD 649
 CURD 650
 CURD 651
 CURD 652
 CURD 653
 CURD 654
 CURD 655
 CURD 656
 CURD 657
 CURD 658
 CURD 659
 CURD 660
 CURD 661
 CURD 662
 CURD 663
 CURD 664
 CURD 665
 CURD 666
 CURD 667
 CURD 668
 CURD 669
 CURD 670
 CURD 671
 CURD 672
 CURD 673
 CURD 674
 CURD 675
 CURD 676
 CURD 677
 CURD 678
 CURD 679
 CURD 680
 CURD 681
 CURD 682
 CURD 683
 CURD 684
 CURD 685
 CURD 686
 CURD 687
 CURD 688
 CURD 689
 CURD 690
 CURD 691
 CURD 692
 CURD 693
 CURD 694
 CURD 695
 CURD 696
 CURD 697
 CURD 698
 CURD 699
 CURD 700
 CURD 701
 CURD 702
 CURD 703
 CURD 704
 CURD 705
 CURD 706
 CURD 707
 CURD 708
 CURD 709
 CURD 710
 CURD 711
 CURD 712
 CURD 713
 CURD 714
 CURD 715
 CURD 716
 CURD 717
 CURD 718
 CURD 719
 CURD 720
 CURD 721
 CURD 722
 CURD 723
 CURD 724
 CURD 725
 CURD 726
 CURD 727
 CURD 728
 CURD 729
 CURD 730
 CURD 731
 CURD 732
 CURD 733
 CURD 734
 CURD 735
 CURD 736
 CURD 737
 CURD 738
 CURD 739
 CURD 740
 CURD 741
 CURD 742
 CURD 743
 CURD 744
 CURD 745
 CURD 746
 CURD 747
 CURD 748
 CURD 749
 CURD 750
 CURD 751
 CURD 752
 CURD 753
 CURD 754
 CURD 755
 CURD 756
 CURD 757
 CURD 758
 CURD 759
 CURD 760
 CURD 761
 CURD 762
 CURD 763
 CURD 764
 CURD 765
 CURD 766
 CURD 767
 CURD 768
 CURD 769
 CURD 770
 CURD 771
 CURD 772
 CURD 773
 CURD 774
 CURD 775
 CURD 776
 CURD 777
 CURD 778
 CURD 779
 CURD 780
 CURD 781
 CURD 782
 CURD 783
 CURD 784
 CURD 785
 CURD 786
 CURD 787
 CURD 788
 CURD 789
 CURD 790
 CURD 791
 CURD 792
 CURD 793
 CURD 794
 CURD 795
 CURD 796
 CURD 797
 CURD 798
 CURD 799
 CURD 800
 CURD 801
 CURD 802
 CURD 803
 CURD 804
 CURD 805
 CURD 806
 CURD 807
 CURD 808
 CURD 809
 CURD 810
 CURD 811
 CURD 812
 CURD 813
 CURD 814
 CURD 815
 CURD 816
 CURD 817
 CURD 818
 CURD 819
 CURD 820
 CURD 821
 CURD 822
 CURD 823
 CURD 824
 CURD 825
 CURD 826
 CURD 827
 CURD 828
 CURD 829
 CURD 830
 CURD 831
 CURD 832
 CURD 833
 CURD 834
 CURD 835
 CURD 836
 CURD 837
 CURD 838
 CURD 839
 CURD 840
 CURD 841
 CURD 842
 CURD 843
 CURD 844
 CURD 845
 CURD 846
 CURD 847
 CURD 848
 CURD 849
 CURD 850
 CURD 851
 CURD 852
 CURD 853
 CURD 854
 CURD 855
 CURD 856
 CURD 857
 CURD 858
 CURD 859
 CURD 860
 CURD 861
 CURD 862
 CURD 863
 CURD 864
 CURD 865
 CURD 866
 CURD 867
 CURD 868
 CURD 869
 CURD 870
 CURD 871
 CURD 872
 CURD 873
 CURD 874
 CURD 875
 CURD 876
 CURD 877
 CURD 878
 CURD 879
 CURD 880
 CURD 881
 CURD 882
 CURD 883
 CURD 884
 CURD 885
 CURD 886
 CURD 887
 CURD 888
 CURD 889
 CURD 890
 CURD 891
 CURD 892
 CURD 893
 CURD 894
 CURD 895
 CURD 896
 CURD 897
 CURD 898
 CURD 899
 CURD 900
 CURD 901
 CURD 902
 CURD 903
 CURD 904
 CURD 905
 CURD 906
 CURD 907
 CURD 908
 CURD 909
 CURD 910
 CURD 911
 CURD 912
 CURD 913
 CURD 914
 CURD 915
 CURD 916
 CURD 917
 CURD 918
 CURD 919
 CURD 920
 CURD 921
 CURD 922
 CURD 923
 CURD 924
 CURD 925
 CURD 926
 CURD 927
 CURD 928
 CURD 929
 CURD 930
 CURD 931
 CURD 932
 CURD 933
 CURD 934
 CURD 935
 CURD 936
 CURD 937
 CURD 938
 CURD 939
 CURD 940
 CURD 941
 CURD 942
 CURD 943
 CURD 944
 CURD 945
 CURD 946
 CURD 947
 CURD 948
 CURD 949
 CURD 950
 CURD 951
 CURD 952
 CURD 953
 CURD 954
 CURD 955
 CURD 956
 CURD 957
 CURD 958
 CURD 959
 CURD 960
 CURD 961
 CURD 962
 CURD 963
 CURD 964
 CURD 965
 CURD 966
 CURD 967
 CURD 968
 CURD 969
 CURD 970
 CURD 971
 CURD 972
 CURD 973
 CURD 974
 CURD 975
 CURD 976
 CURD 977
 CURD 978
 CURD 979
 CURD 980
 CURD 981
 CURD 982
 CURD 983
 CURD 984
 CURD 985
 CURD 986
 CURD 987
 CURD 988
 CURD 989
 CURD 990
 CURD 991
 CURD 992
 CURD 993
 CURD 994
 CURD 995
 CURD 996
 CURD 997
 CURD 998
 CURD 999
 CURD 1000
 CURD 1001
 CURD 1002
 CURD 1003
 CURD 1004
 CURD 1005
 CURD 1006
 CURD 1007
 CURD 1008
 CURD 1009
 CURD 1010
 CURD 1011
 CURD 1012
 CURD 1013
 CURD 1014
 CURD 1015
 CURD 1016
 CURD 1017
 CURD 1018
 CURD 1019
 CURD 1020
 CURD 1021
 CURD 1022
 CURD 1023
 CURD 1024
 CURD 1025
 CURD 1026
 CURD 1027
 CURD 1028
 CURD 1029
 CURD 1030
 CURD 1031
 CURD 1032
 CURD 1033
 CURD 1034
 CURD 1035
 CURD 1036
 CURD 1037
 CURD 1038
 CURD 1039
 CURD 1040
 CURD 1041
 CURD 1042
 CURD 1043
 CURD 1044
 CURD 1045
 CURD 1046
 CURD 1047
 CURD 1048
 CURD 1049
 CURD 1050
 CURD 1051
 CURD 1052
 CURD 1053
 CURD 1054
 CURD 1055
 CURD 1056
 CURD 1057
 CURD 1058
 CURD 1059
 CURD 1060
 CURD 1061
 CURD 1062
 CURD 1063
 CURD 1064
 CURD 1065
 CURD 1066
 CURD 1067
 CURD 1068
 CURD 1069
 CURD 1070
 CURD 1071
 CURD 1072
 CURD 1073
 CURD 1074
 CURD 1075
 CURD 1076
 CURD 1077
 CURD 1078
 CURD 1079
 CURD 1080
 CURD 1081
 CURD 1082
 CURD 1083
 CURD 1084
 CURD 1085
 CURD 1086
 CURD 1087
 CURD 1088
 CURD 1089
 CURD 1090
 CURD 1091
 CURD 1092
 CURD 1093
 CURD 1094
 CURD 1095
 CURD 1096
 CURD 1097
 CURD 1098
 CURD 1099
 CURD 1100
 CURD 1101
 CURD 1102
 CURD 1103
 CURD 1104
 CURD 1105
 CURD 1106
 CURD 1107
 CURD 1108
 CURD 1109
 CURD 1110
 CURD 1111
 CURD 1112
 CURD 1113
 CURD 1114
 CURD 1115
 CURD 1116
 CURD 1117
 CURD 1118
 CURD 1119
 CURD 1120
 CUR

[illegible]

[illegible]

[illegible]

	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
DEB	460.	134.	68.	15618.	
DES	13.	4.	2.	556.	
DES	5.35	6.25	6.34	6.34	
DES	135.94	158.74	160.55	160.95	
CU-PT	228.	267.	270.	270.	
CU-PT	282.	329.	333.	333.	

END-CF-111 JDD HYDROGRAPH ORDINATES

[illegible][illegible]

[illegible][illegible]

7. AT TIME 40.00 HOURS		TOTAL VOLUME	
FEET	642.	72-HOUR	75.
CFS	2557.		772.
CFS	72.		3.
VALUES	7.46		8.80
MIN	189.53		223.54
10-FT	318.		375.
TOTAL CUM	392.		463.

STATION 1, PLAN 1, RATIO 3
END-OF-PLANNED HYDROGRAPH ORDINATES

[illegible]

PEAK FLOOD AND STORAGE (FIELD OF PERIOD) SUMMARY FORMULATED PLAN-RELATED ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS		
				RATIO 1	RATIO 2	RATIO 3
				0.36	0.50	1.00
ADJUSTED AT		0.80 (0.30E 19)	1	1681. (47.59)	2334. (66.09)	4668. (132.19)
ADJUSTED TO		0.80 (0.30E 19)	1	1356. (38.41)	2557. (72.40)	4706. (133.25)
ADJUSTED TO		0.80 (0.30E 19)	1	1356. (38.40)	2554. (72.32)	4709. (133.33)
ADJUSTED TO		0.80 (0.23E 18)	1	1364. (38.61)	2474. (70.07)	4774. (135.20)
ADJUSTED TO		0.80 (0.42E 18)	1	1378. (39.02)	2387. (67.61)	4835. (136.91)
ADJUSTED TO		0.80 (0.61E 13)	1	1391. (39.38)	2180. (61.74)	4886. (138.37)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

RATIO OF PFF	ELEVATION STORAGE OUTFLOW	INITIAL VALUE 1713.00 64. 0.	SPILLWAY CREST 1713.00 64. 0.	TOP OF DAM 1713.50 101. 1362.	TIME OF FAILURE HOURS
1.00	1717.93	1.33	111.	4706.	0.
1.50	1719.14	0.64	106.	2557.	0.
2.00	1719.40	0.	101.	1356.	0.
2.50	1719.40	0.	101.	1356.	0.
3.00	1719.40	0.	101.	1356.	0.
3.50	1719.40	0.	101.	1356.	0.
4.00	1719.40	0.	101.	1356.	0.
4.50	1719.40	0.	101.	1356.	0.
5.00	1719.40	0.	101.	1356.	0.
5.50	1719.40	0.	101.	1356.	0.
6.00	1719.40	0.	101.	1356.	0.
6.50	1719.40	0.	101.	1356.	0.
7.00	1719.40	0.	101.	1356.	0.
7.50	1719.40	0.	101.	1356.	0.
8.00	1719.40	0.	101.	1356.	0.
8.50	1719.40	0.	101.	1356.	0.
9.00	1719.40	0.	101.	1356.	0.
9.50	1719.40	0.	101.	1356.	0.
10.00	1719.40	0.	101.	1356.	0.

PLAN 1 STATION 50

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.36	1356.	1684.2	40.00 2.2
0.50	2554.	1684.7	40.00 2.7
1.00	4709.	1685.8	40.00 3.8

PLAN 1 STATION 1000

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.36	1364.	1621.5	40.17 4.5
0.50	2474.	1622.7	40.00 5.7
1.00	4774.	1624.7	40.00 7.7

PLAN 1 STATION 2000

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.36	1278.	1519.6	40.17 4.6
0.50	2387.	1520.5	40.00 5.5
1.00	4635.	1522.7	40.00 7.7

PLAN 1 STATION 3000

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	TIME HOURS
0.36	1321.	1475.5	40.17 5.5
0.50	2180.	1476.2	40.00 6.2
1.00	4886.	1478.0	40.00 8.0

FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 26 FEB 79
MODIFIED FOR HONEYWELL APL 79

A1 ROXBURY DAM
A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

NEW YORK STATE
DEPT OF ENVIRONMENTAL CONSERVATION
FLOOD PROTECTION BUREAU

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

A PHF WITH RATIOS - ANALYSIS
A3 DATE
B 200 0 10 0 0 0 0 0
B1 5

33

K 1 1000

34

K1 LOCATION HILLSIDE

35

Y 1 1

36

Y1 1

37

Y6 .05 .05 1617 1660 1000 .065

38

Y7 0 1660 30 1640 110 1620 115 1617 125 1617

39

Y7 130 1620 190 1640 220 1660

40

K 1 2000

41

K1 LOCATION ROAD CROSSING

42

Y 1 1

43

Y1 1

44

Y6 .05 .05 1515 1600 1000 .10

45

Y7 0 1600 400 1560 780 1520 780 1515 795 1515

46

Y7 795 1520 1000 1540 1200 1600

47

K 1 3000

48

K1 LOCATION JUNCTION WITH EAST BRANCH OF DELAWARE

49

Y 1 1

50

Y1 1

51

Y6 .05 .05 1470 1520 1000 .04

52

Y7 0 1520 50 1500 1050 1475 1050 1470 1065 1470

53

Y7 1065 1475 2000 1500 2150 1520

54

K 99

55

A

56

A

57

A

58

A

59

A

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FORMULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS		
				RATIO 1	RATIO 2	RATIO 3
				0.37	0.50	1.00
HYDROGRAPH AT	1	0.80 (0.30E 19)	1	1727. (48.91)(2334. 66.09)(4668. 132.19)(
ROUTED TO	1	0.80 (0.30E 19)	1	2040. (57.78)(2937. 83.17)(5066. 143.44)(
ROUTED TO	50	0.80 (0.30E 19)	1	2042. (57.83)(2939. 83.23)(5068. 143.52)(
ROUTED TO	1000	0.80 (0.23E 18)	1	2071. (58.65)(2970. 84.10)(5131. 145.28)(
ROUTED TO	2000	0.80 (0.42E 18)	1	2087. (59.11)(2986. 84.56)(5183. 146.76)(
ROUTED TO	3000	0.80 (0.61E 18)	1	2077. (58.83)(2956. 83.72)(5231. 148.12)(

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	ELEVATION STORAGE OUTFLOW	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM	TIME OF FAILURE HOURS
0.37	1718.61	1718.00	1713.00	1713.00	1718.50	40.00
0.50	1718.90	64.	64.	64.	101.	39.83
1.00	1719.41	0.	0.	0.	1362.	39.67

PLAN 1 STATION 50

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	DURATION OVER TOP HOURS	TIME HOURS
0.37	2042.	1684.5	0.25	40.33 2.5
0.50	2939.	1684.9	0.35	40.17 2.9
1.00	5068.	1685.9	0.54	40.00 3.1

PLAN 1 STATION 1000

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	DURATION OVER TOP HOURS	TIME HOURS
0.37	2071.	1622.3	0.33	40.33 2.3
0.50	2970.	1623.3	0.47	40.17 6.3
1.00	5131.	1624.9	0.77	40.00 7.7

PLAN 1 STATION 2000

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	DURATION OVER TOP HOURS	TIME HOURS
0.37	2087.	1520.2	0.52	40.33 5.2
0.50	2986.	1521.1	0.71	40.17 6.1
1.00	5183.	1523.1	0.81	40.00 8.1

PLAN 1 STATION 3000

RATIO	MAXIMUM FLOW, CFS	MAXIMUM STAGE, FT	DURATION OVER TOP HOURS	TIME HOURS
0.37	2077.	1476.1	0.61	40.33 6.1
0.50	2956.	1476.7	0.77	40.17 6.7
1.00	5231.	1478.1	0.81	40.00 8.1

APPENDIX D
STABILITY COMPUTATIONS

PROJECT GRID

JOB ROXBURY DAM	SHEET NO. 1	CHECKED BY	DATE
SUBJECT STRUCTURAL STABILITY ANALYSIS		COMPUTED BY RLW	DATE 2/27/80

ADD VOLUME ON TO ACCOUNT FOR ABUTMENT AND PIERS

VOLUME OF WEST ABUTMENT $(8')(10.5')(10) = 840 \text{ ft}^3$

VOLUME OF EAST ABUTMENT $(3.5')(10.5')(12) = 441 \text{ ft}^3$

VOLUME OF PIERS $(4')(2')(10)(5) = 400 \text{ ft}^3$

1681 ft^3

DIVIDE THIS BY WIDTH OF FRONT SLAB

$\frac{1681 \text{ ft}^3}{34 \text{ ft}} = 49.4 \text{ ft}^3/\text{ft}$

ADD THIS TO THE SECTION ANALYZED

AREAS CAN BE COMBINED AND TAKEN AS 1 AREA

AREA = $(1) + (2) + (3) = (1)(5) + (2)(10) + (5)(10) = 75 \text{ ft}^2$

DISTANCE FROM CENTROID TO DOWNSTREAM TOE = 5'

INPUT TO STABILITY ANALYSIS PROGRAM

<u>INPUT ENTRY</u>	<u>PROGRAM No.</u>
Unit Weight of Dam (K/ft^3)	0
Area of Segment No. 1 (ft^2)	1
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2
Area of Segment No. 2 (ft^2)	3
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4
Area of Segment No. 3 (ft^2)	5
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6
Base Width of Dam (Total) (ft)	7
Height of Dam (ft)	8
Ice Loading (K/L ft.)	9
Coefficient of Sliding	10
Unit Weight of Soil (K/ft^3)	11
Active Soil Coefficient - K_a	12
Passive Soil Coefficient - K_p	13
Height of Water over Top of Dam or Spillway (ft)	14
Height of Soil for Active Pressure (ft)	15
Height of Soil for Passive Pressure (ft)	16
Height of Water in Tailrace Channel (ft)	17
Weight of Water (K/ft^3)	18
Area of Segment No. 4 (ft^2)	19
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20
Height of Ice Load or Active Water (ft)	46

NORMAL CONDITIONS

P

0.15	RCL
	1
75.	
75.	RCL
	2
5.	
5.	RCL
	3
0.	
0.	RCL
	4
0.	
0.	RCL
	7
11.	
11.	RCL
	8
7.	
7.	RCL
	9
0.	
0.	RCL
	10
0.5	
0.5	RCL
	11
0.055	
0.055	RCL
	14
0.	
0.	RCL
	18
0.0624	
0.0624	RCL
	46
7.	

ICE LOAD OF 5KSF

0.15	RCL
	1
75.	
75.	RCL
	2
5.	
5.	RCL
	3
0.	
0.	RCL
	4
0.	
0.	RCL
	7
11.	
11.	RCL
	8
7.	
7.	RCL
	9
5.	
5.	RCL
	10
0.5	
0.5	RCL
	11
0.055	
0.055	RCL
	14
0.	
0.	RCL
	18
0.0624	
0.0624	RCL
	46
7.	

2.655205619 ————— FS. VS. OVERTURNING — 1.001160456

3.96324427 ————— .0073692301

2.893642072 ————— FS. VS. SLIDING — .6775824041

SEISMIC STUDY

WATER SURFACE AT
TOP OF DAM

0.15	RCL 1	0.15	RCL 1
75.		75.	
75.	RCL 2	75.	RCL 2
5.		5.	
5.	RCL 3	5.	RCL 3
0.		0.	
0.	RCL 4	0.	RCL 4
0.		0.	
0.	RCL 7	0.	RCL 7
11.		11.	
11.	RCL 8	11.	RCL 8
7.		7.	
7.	RCL 9	7.	RCL 9
0.		0.	
0.	RCL 10	0.	RCL 10
0.5		0.5	
0.5	RCL 11	0.5	RCL 11
0.055		0.055	
0.055	RCL 14	0.055	RCL 14
5.5		0.	
5.5	RCL 18	0.	RCL 18
0.0624		0.0624	
0.0624	RCL 46	0.0624	RCL 46
7.		7.	
		7.	RCL 50
		0.1	

NORMAL

2.655205619

3.96324427

2.893642072

SEISMIC

2.061609165

3.273824314

1.566867611

1.900774502

F.S. vs. OVERTURNING

3.01288485

1.12500525

F.S. vs. SLIDING

APPENDIX E

REFERENCES


APPENDIX E

REFERENCES


- 1) U.S. Department of Commerce, Technical Paper No. 40, Rainfall Frequency Atlas of the United States, May 1961.
- 2) H.W. King and E.F. Brater, Handbook of Hydraulics, 5th edition, McGraw-Hill, 1963.
- 3) University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1973.
- 4) Elwyn E. Seelye, Design, 3rd edition, John Wiley and Sons, Inc., 1960
- 5) U.S. Department of the Interior, Bureau of Reclamation; Design of Small Dams, 2nd edition (rev. reprint), 1977.
- 6) U.S. Army, Corps of Engineers, Upper Delaware River Basin Hydrologic Flood Routing Model, October, 1976

APPENDIX F

DRAWINGS



VICINITY MAP
ROXBURY DAM
I.D. No. NY 788



TOPOGRAPHIC MAP
ROXBURY DAM
I.D. No. NY 788

MS

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
ALBANY, NEW YORK 12201

FOR DEPARTMENT USE ONLY

Application No. 413-16-0082Dam No. 646Watershed Delaware Bas.

APPLICATION FOR PERMIT

for the Construction, Reconstruction or Repair of a Dam or
Other Impoundment Structure under Conservation Law, Section 429 (c).

Instructions on the reverse side before completing this application. Please type or print clearly in ink.

1. NAME AND ADDRESS OF APPLICANT

First Name M.I. Last Name Phone No. 212
Chantex Corporation 752 - 5220

Street Address
850 3rd. Ave.

Post Office State Zip Code
New York City N.Y. 10000

2. NAME AND ADDRESS OF OWNER (if different from applicant)

First Name M.I. Last Name
Chantex Corporation

Street Address
850 3rd. Ave.

Post Office State Zip Code
New York City N.Y. 10000

3. TYPE OF PROJECT

☐ Construction ☒ Reconstruction ☐ Repair

4. IS STATE-OWNED LAND TO BE USED?

☐ Yes ☒ No

5. PROPOSED STARTING DATE

July 1, 1976

6. EXPECTED COMPLETION DATE

July 30, 1977

7. PROJECT DESCRIPTION

A. LOCATION OF DAM

Stream or Body of Water tributary of the County Delaware Town Roxbury
branch of Delaware R. Give direction and distance from commonly accepted landmark
1/2 mi. S. to 300' E. from intersection of
Highway 30 & County Rd. 47 in Roxbury NY

B. LOCATION ON U.S. GEOLOGICAL SURVEY MAP

Name of Map Roxbury Latitude 42°-17'-27" Longitude 74°-34'-14" Recreation

8. PROPOSED USE FOR IMPOUNDED WATER Recreation

9. STATE THE HEIGHT ABOVE SPILLCREST OF THE LOWEST PART OF THE IMMEDIATE UPSTREAM ADJOINING PROPERTY OR PROPERTIES

Unknown Feet

10. IS THIS PROPOSED POND OR LAKE PART OF A PUBLIC WATER SUPPLY? ☐ Yes ☒ No
If not, where is nearest downstream public water supply intake? Margaretville, or Roxbury

11. SIZE OF AREA DRAINING INTO POND OR LAKE (Acres or Square Miles)
490 Acres

12. THE DRAINAGE AREA IS COMPOSED OF: (Total = 100%)

30 % Forest 40 % Cropland 30 % Pasture 0 % Other 0 % Swamp 0 % Suburban Lands 0 % Urban Lands

13. TYPE OF SPILLWAY

☒ Service Spillway - Auxiliary Spillway Combination
☐ Single Spillway
☐ Pipe Riser ONLY
☐ Other

14. DESIGNER'S ESTIMATE OF CLASS OF HAZARD (As described in "Guidelines for Small Earth Dam Designs")

☐ Class "a" ☐ Class "b" ☒ Class "c"

NOTE: Provide descriptive information on character of downstream area.

15. SPILLWAY INFLOW DESIGN FLOOD

Frequency 100yr Flood Peak 670 c.f.s. Runoff Volume 6"/24hr.

16. SERVICE SPILLWAY INFLOW DESIGN FLOOD

Frequency 100yr Flood Peak 360 c.f.s. Runoff Volume 4.4"/24hr.

17. THE SINGLE SPILLWAY OR AUXILIARY SPILLWAY IS COMPOSED OF:

☒ Vegetated Earth ☐ Concrete ☐ Timber ☐ Rock-filled Crib ☒ Masonry ☐ Other

18. MAXIMUM VELOCITY WITHIN THE SINGLE OR AUXILIARY SPILLWAY

7 f.p.s. DISCHARGE AT DESIGN HIGH WATER 154 c.f.s.

19. TYPE OF ENERGY DISSIPATER PROVIDED ON SINGLE SPILLWAY

☐ Hydraulic Jump Basin ☐ Drop Structure ☒ Other III

20. POND OR LAKE WILL BE DRAINED BY MEANS OF

12 inch
sloting Pipe thru Dam

21. WATER WILL BE SUPPLIED TO RIPARIAN OWNERS DOWNSTREAM BY MEANS OF

Concrete Spillway

22. HEIGHT OF DAM ABOVE STREAM BED

35.5 Feet

23. AREA-CAPACITY DATA

Answer 1, 2 and 3, OR 1, 2, 4, 5

ELEVATION,

Referred To Assumed Benchmark

SURFACE AREA

VOLUME STORED

	ELEVATION, Feet	SURFACE AREA, Acres	VOLUME STORED, Acre-Feet
Top of Dam	<u>1718.5</u>	<u>7.8</u>	<u>101.0</u>
Design High Water	<u>1717.5</u>	<u>7.5</u>	<u>93.4</u>
Single Spillway Crest	<u>1715.5</u>	<u>7.0</u>	<u>70.5</u>
Auxiliary Spillway Crest	<u>1713.0</u>	<u>5.8</u>	<u>63.9</u>
Service Spillway Crest			

24. TYPE OF ENERGY DISSIPATER AT OUTLET OF CONDUIT:

☐ Impact Basin ☐ Plunge Pool ☐ Hydraulic Jump Basin ☒ Other III

25. IS PIPE RISER PROVIDED WITH AN ANTI-VORTEX DEVICE?

☐ Yes ☒ No III

26. RAWDOWN TIMES: Answer 1 and 2, or 1, 3 and 4

Has provision been made to evacuate 90% of the storage below the lowest spillway crest within fourteen days? ☒ Yes ☐ No

Can the single spillway evacuate 75% of the storage between the maximum design high water and the spillway crest within 48 hours? ☐ Yes ☒ No

Can the Service Spillway evacuate 75% of the storage between the auxiliary spillway and the Service Spillway crests within seven days? ☒ Yes ☐ No

Can the Service Spillway and the Auxiliary Spillway in combination evacuate the storage between the design high water and the auxiliary spillway crest within 12 hours? ☐ Yes ☒ No

24. SOIL DATA — State the character of the bed and banks in respect to natural types of soil materials, hardness, perviousness, water bearing, effect of exposure to air and water, uniformity, etc.

HA

If an earth dam, describe the material to be used in the embankment.

HA

What is the source of embankment fill material(s)?

HA

Are there porous seams or fissures beneath the foundation of the proposed dam? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Method used to obtain the above soil data <input type="checkbox"/> Soil Borings <input type="checkbox"/> Test Pits	
25. DESIGN ENGINEER Name of Agency or Individual Richard P. Duck, P.E.		P.E. License No. of Individual # 45665	
Address Box 258A, RD #1, Depositt, N.Y. 13754		Address Box 258A RD #1, Depositt, N.Y. 13754	
Title Consulting Engineer		Title Consulting Engineer	

27. NAME AND ADDRESS OF OFFICIAL NEWSPAPER OF LOCALITY WHERE PROPOSED WORKS ARE LOCATED

Catskill Mountain News, Margeroville, New York 12455

CERTIFICATION

28. Application is hereby made to the Department of Environmental Conservation pursuant to Section 429(c) of the Conservation Law.

The applicant certifies that the above statements are true and agrees that the issuance of the permit is based on the accuracy thereof. As a condition to the issuance of a permit, the applicant accepts full legal responsibility for all damage, direct or indirect, of whatever nature, and by whomever suffered, arising out of the project described herein and agrees to indemnify and save harmless the State from suits, actions, damages and costs of every name and description resulting from the said project.

June 21, 1976

Date

Richard P. Duck

Signature

INSTRUCTIONS

1. Type or print in INK.
2. Five (5) copies of all papers including detail construction plans and specifications must be filed.
3. The plans and specifications submitted with the application must include the following information:
 - (a) A plan showing proposed dam, dam appurtenances, bench marks, topographic contours at dam and around the anticipated reservoir area, including 2-foot contours to 6 feet above high water level.
 - (b) A profile along the dam axis and a transverse section of the dam at its maximum height.
 - (c) A profile along the center line and transverse section, or sections, of the spillways including stilling basins, outlet work, and other details, if necessary, in design of the structures.
 - (d) A topographical plan to a suitable scale showing drainage area, normal water level in the lake or pond and owners property line notes and bounds.
 - (e) Specifications for materials and methods of construction.
 - (f) A log of all soil information available to the design engineer or conservationist and location of drill holes, test pits or other foundation exploration, location of borrow area, horizontal and vertical controls, if necessary.
 - (g) Additional drawings should be included to clearly show all details of the proposed works.
4. NO WORK of construction, reconstruction or repairs of the structure or structures SHALL BE STARTED UNTIL A PERMIT therefor has been issued by the New York State Department of Environmental Conservation.
5. The design, preparation of plans, estimates and specifications and the supervision of the erection, reconstruction and repair of all the structures herein applied for shall be done by a licensed professional engineer, or in the case of farm ponds by an engineer or conservationist employed by a governmental agency cooperating with a soil conservation district, or by an engineer employed by the Department of Environmental Conservation.
6. A "Notice of Application" must be published by the applicant. The form of notice and instructions for publication will be furnished to the applicant by the Local Permit Agent to whom the application is delivered.
7. An information circular "Guidelines for Small Earth Dam Designs" is available upon request from the Department of Environmental Conservation or the Local Permit Agent.
8. Samples of foundation, embankment and construction material need not be furnished unless requested.


PROPOSED PLAN FOR PASSAGE OF OUTLET PIPE

THROUGH KIRKSIDE PARK DAM

SEPTEMBER 1912

 = Concrete.

Scale 1" = 10'-0"



SECTION NEAR "E"

SECTION "D-D"

From 6' to 9' GATE HOUSE

APPROXIMATE LOCATION AND DIMENSIONS
CONCRETE WALLS AT LEAST 18" THICK

PIPE SURROUNDED BY
AT LEAST 18" OF CONCRETE

ABOUT 7' - Extra Fill


NEW PAVED SURFACE
OLD PAVED SURFACE
SUMED EARTH

APPROXIMATE LEVEL OF WATER
SEPTEMBER 1912.


RIDDLE GORE WALL

ORIGINAL SURFACE

NEAR "E-E."



LOCATION FOR NEW EMERGENCY
SPILLWAY - SHEET 3



WEIR AND
PIS

1625

1620

CONDUIT

ING
M

TRUE

N


17.85

NEW NORMAL FOR
1713.0

1710

1705


5.8 ACRES @ 1713.0



LOCATION MAP

SCALE: 1" = 2000'


U.S.G.S. QUADRANGLE MAP - ROXBURY, NY.



LOCATION MAP


SCALE: 1" = 2000'

ORANGE MAP - ROXBURY, NY. - 1945



NOTE: CONTOUR LINES 1715' AND 1720'
ON UPSTREAM SIDE OF DAM ARE ASSUMED.

NOTES:
PA
1123
PA
PA
PA
PA



NOTE: CONTAIN MAP SHOWING FORMER
 PLANNED BY NEW YORK STATE IN 1912 -
 APPROVED ON OCTOBER 7, 1912 BY STATE
 OF N.Y. CONSERVATION COMMISSION, DIVISION
 OF INLAND WATER - APPROVED NO. 646.
 ALL EXISTING OUTLET CHANNELS ARE TAKEN
 FROM SAME PLANS.

ORIGINAL FLOW LINE
ON MAP OF 1912
D. 6 3

REPORT OF
DALES LAKE DAM
(SHEPHERD LAKE)
TOWN OF ROXBURY, CO. AYER & C.

WATERED AREA - 40
HEIGHT OF DAM - 25
FLOOD LEVEL - 15

INDEX

1. OVERVIEW AND STORAGE AREA
2. MAIN LINEWAY REPAIRS
3. EMERGENCY LINEWAY DETAIL

Richard A. Buck

SHEET 1 OF 3

COVER SHEET AND
STORAGE AREAS

FOR

DALES LAKE DAM

(SHEPHERD LAKE)
OWNERS: CHESTER CORPORATION

TOWN OF ROXBURY - DELAWARE COUNTY
NEW YORK STATE


DESIGNED BY:


RICHARD A. BUCK AND ASSOCIATES
OFFICE: NEW YORK

SCALE: 1" = 100'

JUNE 16, 1958

MAP NO. 719





100' 0" 64'
 50' 0" 00'

REPAIR WA
 A. 100' 0" 64'
 N 100' 0" 00'

LIPSTREAM

SEALIFY CONCRETE SURFACE
PIERS AND ABUTMENTS (XXX) THEN
POURING NEW WALL.

CONCRETE BOTTOM

#4 BARS
12" ON CENTER
BOTH WAYS

1 MIN
COVER OVER
#4 BARS.

CONCRETE 4200 PSI

12"

CONCRETE
WALL

REMOVE
ALL
RAVINES

ABUTMENT

TOP OF 8" W-
SILL 205'S

ELEV. 1708.12

DOWNSTREAM

REPAIR W.R.G. WALL
AS ORDERED BY ENGINEER
IN THE FIELD


NOTE: ALL BRIDGE DECKING IS TO BE
REMOVED.




KEY NEW WALL INTO WINGS
AND ABUTMENT AS SHOWN -
SEAL WITH GROUT AND MASTIC

FILL

DOWN TR.



PLAN VIEW



ELEVATION


EXISTING MAIN
SCALE 1" = 5'

REAM

AS
IN

VIEW

TOP OF
ELEV.



SPILLWAY

AS ORDERED BY ENGINEER
IN THE FIELD

DOWNSTREAM

NOTE: ALL BRIDGE DECKING IS TO BE
REMOVED.

PLAN VIEW

TOP OF CAN.
ELEV. 1709.52

ABUTMENT

REMOVE PIER CONCRETE DOWN TO
ELEV. 1712.75' THEN ADD 3"
NEW CONCRETE FOR CAP.

NORMAL POOL @
ELEV. 1712.0'

2" MIN COVER OVER
REBARS FOR NEW BOTTOM

ELEV. 1708.11'

KEY NEW
SLAB AS
GRILLAGE

ELEVATION

PROPOSED MAIN SPILLWAY

SCALE: 1" = 5'

ELEV. 79.5'

ABUTMENT

CONCRETE SLAB

WALL INTO BOTTOM
DOWN - SEAL WITH
CONCRETE

Richard P. Buck

SHEET 2 OF 3

MAIN SPILLWAY REPAIRS

FOR

DALES LAKE DAM

OWNER: ^{SHEPHERD LAKE} CHEMTEX CORPORATION
TOWN OF AYRWAY - DELAWARE COUNTY
NEW YORK STATE

DESIGNED BY:


RICHARD P. BUCK AND ASSOCIATES
DEPT. 1, NEW YORK

SCALE: AS SHOWN

JUNE 15, 1978


MAP NO. 768

8



ELEVATION - E C

ORIGINAL



ELEVATION - E CHANNEL



AD-A087 588

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION ALBANY F/6 13/13
NATIONAL DAM SAFETY PROGRAM. ROXBURY DAM (INVENTORY NUMBER 788)--ETC(U)
MAY 80 G KOCH

DACW51-79-C-0001
NL


UNCLASSIFIED

2 of 2

AD-A087 588



END
7-70




PLAN

EXISTING EMERG

SCALE: 1" = 10'

NOTE: EXISTING PLANS FOR SP. OF 1912 - SEE SHEET 97




PLAN VIEW

EXISTING EMERGENCY SPILLWAY

SCALE: 1" = 5'

NOTE: EXISTING PLANS FOR SPILLWAY AS TAKEN FROM PLANS OF 1912 - SEE SHEET # 1 NOTE.



ELEVATION

E
DAM

REMOVED SCREENS
AND POSTS

TOP OF DAM - ELEV 118.5

NEW NORM
ELEV.


CONCRETE WEIR

E
DAM

ELEVATION - E CHANNEL

E
DAM

REMOVE ALL
OLD BR. WORK




REMOVED SCREENS
AND POSTS

TOP OF DAM - ELEV. 1748.5'

NEW NORMAL POOL
ELEV. 1713.0'

CONCRETE WEIR



A technical drawing showing a proposed channel layout. The drawing includes two sections of a channel, each bounded by a 'Laid Stone Wall'. A 'New Channel Bottom' is indicated with a dashed line and an elevation of 1745.8'. A 'Slope Hydrap' is shown connecting the two channel sections, with a note to 'Match or Final Channel Slope'. The drawing is oriented diagonally on the page.

SLOPE HYDRAP TO
MATCH OR FINAL
CHANNEL SLOPE

Laid Stone Wall

NEW
CHANNEL
BOTTOM -

ELEV. = 1745.8'

Laid Stone Wall

PROPOSED

REMOVE ALL
OLD WORK

Laid stone with
grouted joints -
min. of 40" stone

REMOVE CONCRETE POSTS
TO BELOW ELEV 715.5 -
ALSO REMOVE ALL FISH
SCREENS.

TOP OF DAM
ELEV 718.5' ±

DAM

NOTE: ENTIRE CONCRETE WALL ABOVE TO
BE REMOVED IF SO ORDERED BY ENGINEER
AFTER HIS ON-SITE INSPECTION. REPLACE WITH
IMPERVIOUS FILL AND SLOPE TO POND
BOTTOM @ 113.

NOTE: CHANNEL WALLS TO BE SEALED WITH
GROUT IF SO ORDERED BY ENGINEER.

PLAN VIEW

ED. EMERGENCY SPILLWAY

SCALE 1" = 5'

EM

D

ONE
TOWN

WITH
75 -
STONE

REMOVE CONCRETE POSTS
TO BELOW ELEV 715.5 -
ALSO REMOVE ALL FISH
SCREENS.

CONCRETE WALL ADJACENT TO
IF SO ORDERED BY ENGINEER
FOR INSPECTION. REPLACE WITH
FILL AND SLOPE TO ROAD
113.

WALLS TO BE SEALED WITH
SO ORDERED BY ENGINEER.

EMERGENCY SPILLWAYS
DETAILS

FOR

DALES LAKE DAM
(SHEPHERD LAKE)

DAM - CENTER CONNECTION
TOWN OF ROXBURY - DELAWARE COUNTY
NEW YORK STATE

DESIGNED BY J. H. HARRIS
ENGINEER, NEW YORK

SCALE: AS SHOWN

JULY 25, 1954

NO. 100-749